BORING

Portable Magnetic Base Drilling Machine

ATRA ACE manual feed

Model ARA-100A CC • Max. 100 mm dia. x 75 mm deep

274 mm

The versatile drilling machine with top-class power

- Accepts various cutters for diverse drilling
- Advanced electronic control for efficient drilling and operator safety

Model				ARA-100A	
Power Source (Single Phase)				220 - 240 V AC, 50/60 Hz	
Electric	Rated Power Consumption W		1800		
Drill	Rated Current A			8.2	
	No-load Speed min ⁻¹ (rpm)		110 - 210 / 330 - 660		
	Morse Taper No.			MT3	
	Rated Duty min		min	30	
Magnet Power Consumption W				80	
Hole	Cutte	r		Hole Diameter	Plate Thickness
Capacity mm	One-touch Type JETBROACH 35L			17.5 to 40	13 to 35
	One-touch Type JETBROACH 50L			17.5 to 50	13 to 50
	One-touch Type JETBROACH 75L			17.5 to 50	13 to 75
	JETBROACH 75L			50 to 100	13 to 75
	One-touch Type HI-BROACH 25L			17.5 to 35	13 to 25
	One-touch Type HI-BROACH 50L			18 to 35	13 to 50
	Twist Drill			Max. 32 mm dia.	
Max. Stroke mm			mm	296	
Magnet Holding Power N(kgf)			N(kgf)	17000 (1733)	
Magnet Dimensions mm			mm	110 x 220	
Cutter Position Straight Front to Bac		o Back mm	20		
Adjustment Swivel angle			30°		
Power Cord Length m			m	5	
Mass (Weight) kg			kg	30	

Accessories Included

Pilot Pin 12075

Drill Drift

- Side Handle
- 2.5 mm Hex. Socket Screw Key • 5 mm Hex. Socket Screw Key
- 6 mm Hex. Socket Screw Key
- 8 mm Hex. Socket Screw Key
- Oil Tank
 Oil Tank Bracket
 3 pieces of Rod Handle

Guard

• 7 x 8 mm Spanner

Safety Chain


- Holder MT03075 Side Lock
- **Optional Accessories**

Ref. No. PN		Description	Sales Unit		
1	TB01507	Cutting Oil 2L			
2	TB04374	Supporting Magnet Ass'y	1 piece		
3	TB09727	Holder MT03075 One-touch			

Slow Starting Function


Slow speed at the beginning of boring will securely set a hole cutting position.





Two speed electric drill with speed adjustment

Optimum drill speed adjustment can be made to bore a hole on difficult-to-cut materials or to securely set a hole cutting position at initial cutting stage.





Shift Lever

BORING

Load Indication and LED Condition

Load Indication


The load indicator (LED) indicates the condition of the load with different color of LED light.

- The LED lights up in red. The I FD blinks in red
- The LED lights up in green.

 The load on the drill motor is normal. The load on the drill motor is close to overload. The drill motor is overloaded.

Automatic Stop Function

As the drilling load increases, the load indicator will change in color from green to red. In addition, if excessive feeding force is applied, the load indicator will rapidly blink red and the rotation of the drill motor will slow down and stop. After the drill motor has come to a complete stop, the load indicator will slowly blink in green. To resume the rotation of the drill motor release the load and turn off the switch of the drill motor, and then turn it on.



Built-in Motion Sensor

If any lateral movement or excess vibration is detected during drilling a hole, the drill motor stop instantly and the LED blink red. To resume operation, turn the magnet switch off and on.



Fail-safe Restart

The magnetic field will become active, but the drill will not re-start even if power is re-supplied after accidental shutdown. The LED will blink green at this stage. Drilling can only be continued after turning on the drill switch.

Magnet Open-circuit Sensor

The drill will not start until the magnetic field is active. If malfunction occurs on the magnet, the LED will blink red slowly and the drill motor will not revolve.




Features

Reversible Feed Handles

Feed handles can be positioned on the right or left hand side for ease of drilling. When changing the feed handle position, oil tank is required to be positioned opposite to the feed

Drilling Position Adjustment



When the clamp lever is loosened, the drill position can be adjusted back and forth by 20 mm and pivoted 15 degrees to the left or right. The clamp lever can be positioned for left hand or right hand operation

One-Touch Cutter Replacement (Holder MT03075 One-Touch) Mounting the cutter Align the depression in the cutter



handles.

shank with the white line on the sleeve, and then insert the cutter.



Removing the cutter Turn the sleeve counterclockwise. The cutter will come off.



Available in the market

MT3

Twist Drill Bit



Drill chuck Arbor MT3 Straight **Drill Rit** Drill

MT3 Morse taper shank drill bit can be directly installed.

Use Morse taper sleeve MT3 for other sizes than MT3

A drill chuck is required to install a straight drill bit.

Chuck